

## **14.0 REFERENCES AND SUPPORTING DOCUMENTATION**

ADANAC MOLY CORPORATION, 2006; Application for an Environmental Assessment Certificate for the Ruby Creek Molybdenum Project.

ASH, C.H., 2004; Geology of the Atlin Map Area, Northern British Columbia: BC Ministry of Energy and Mines Geoscience Map 2004-4.

ASH, C.H., 2001; Ophiolite Related Gold Quartz Veins in the North American Cordillera: BC Ministry of Energy and Mines Bulletin 108.

BGC ENGINEERING INC., 2006; Hydrogeological Investigation and Analyses Report – Proposed Excavation.

BGC ENGINEERING INC., 2006; Pine Creek Diversion Report.

BLACK, J.M., 1953; Report on the Atlin Placer Camp: BC Ministry of Mines.

BGC ENGINEERING INC., 2006; Pine Creek Diversion.

CONNOR, M., 2009; Fisheries Summary for Prize Mining Site.

CRC, 1985; CRC Handbook of Chemistry and Physics.

DANDY, L., 2006; Geology, Geophysics and Drilling Report on the Atlin Gold Property: BC Ministry of Energy and Mines Assessment Report.

DANDY, L., 2005; Geology, Geophysics and Drilling Report on the Atlin Gold Property: Internal Report for Prize Mining Corp.

DANDY, L., 2005; Technical Report on the Atlin Gold Property.

ENVIRONMENT CANADA, National Climate Data and International Archive

ERHARDT, R. and CONNOR, M., 2006; Biological Assessment of the Atlin Hydroelectric Project, Taku Land Corporation: Unpublished report.

EVANS, B., 2003; Geological Report on the Muskox Minerals Corp. Yellowjacket Property.

G & T METALLURGICAL SERVICES, 2006; Preliminary Assessment of Yellowjacket Metallurgy.

HALL, T & ASSOCIATES, 2006; Guide to Preparing a Mine Permit Application Under the British Columbia Mines Act: prepared for Mining and Minerals Division, Ministry of Energy, Mines and Petroleum Resources.

HEALTH, SAFETY AND RECLAMATION CODE FOR MINES IN BC; 2008: BC Ministry of Energy, Mines and Petroleum Resources.

LEVSON, V.M., 1992; Report on Geology in the Atlin Area: BC Ministry of Energy and Mines.

LORAX ENVIRONMENTAL SERVICES INC., 2009; 2009 Yellowjacket Water Quality and Waste Sampling Program: Technical Memorandum.

LORAX ENVIRONMENTAL SERVICES INC., 2009; 2009 Yellowjacket Water Quality Monitoring: Memorandum.

LORAX ENVIRONMENTAL SERVICES INC., 2009; Yellowjacket Gold Project Baseline Water Quality Conditions (2006-2007 Monitoring).

LORAX ENVIRONMENTAL SERVICES INC., 2009; Yellowjacket Property Bulk Sample Waste Characterization Program.

MEMPR, 1991; Dump Stability Rating Scheme in Investigation and Design Manual Interim Guidelines and Dump Stability Classes and Recommended Level of Effort in Investigation and Design Manual Interim Guidelines

PENDRAY, T., 1983; Stream Habitat Evaluation for Two Study Areas within the Yukon River Basins in Canada: Department of Renewable Resources Yukon Territorial Government, Yukon River Basin Study Technical Report, Fisheries No.3. 1983.

PRICE, W.A., 1997; Draft Guidelines and Recommended Methods for Prediction of Metal Leaching and Acid Rock Drainage at Minesites in British Columbia: BC Ministry of Energy and Mines.

SIGMA ENGINEERING, 2006; Atlin Hydroelectric Project Hydrology Report.

SPARLING, P.; 2006; Pine Creek Diversion, Fish Salvage: White Mountain Environmental Consulting, Unpublished report.

STEWART, C., 2009; Ministry of Environment Response Letter to NWMDRC Presentation and Submission.

TAKU LAND CORP, 2006; Atlin Hydroelectric Project – Environmental Impact Statement, CEAA.

TAKU RIVER TLINGIT FIRST NATION, 2007; Mining Policy.

TAKU RIVER TLINGIT FIRST NATION, 2003; Our Land is Our Future: Há tlátgi há khustiyxh siti: Vision & Management Direction for Land and Resources.